

Key	Changelog statement	Component/s
Bug QDC-2639	The quick launch bar disappeared after using an icon several times. Bug fixed.	O-QIS, procella
Bug QDC-3098	Additional data window showed too many times during measurement. Bug fixed.	O-QIS, procella
Bug QDC-3170	The problem that previously issued (historical) alarms were displayed again when uploading position tolerances in O-QIS MCA/CMM Reporting for single-value alarms has been resolved.	O-QIS
Bug QDC-3211	After alarm only a characteristic or group of characteristic will be restarted from qualification phase during Dynamic inspation.	O-QIS
Bug QDC-3676	Access violation in CMM upload fixed	M-QIS Upload
Bug QDC-3709	Stored fields for the takeover / copy function were duplicated after several hours of running time in Q-DM	M-QIS Upload
Bug QDC-3711	Access violation when starting CMM Reporting. As a result, the graphics were displayed without content. Error fixed.	O-QIS
Bug QDC-3724	Access violation when calling the special measurement has been fixed.	procella
Bug QDC-3783	Measurement procedure corrected for recording characteristics and characteristic groups with different subgroup sizes.	O-QIS, procella
Bug QDC-3850	Access violation in live operation in CMM reporting if Access buffer databases are used in combination with the "Compress database" option. Error fixed.	O-QIS
Bug QDC-3868	For newly created VDA5 studies, it was no longer possible to specify measured values for the measurement system.	solara
Bug QDC-3951	The calculation of %GRR (%R&R) for characteristics with only one specification limit was incorrect.	solara