

	Key	Changelog statement	Component/s
Bug	QDC-3883	The problem with using custom buttons in the application bar has been fixed.	O-QIS, procella
Bug	QDC-4093	Unwanted repeating of alarmed values in Dynamic sampling. Bug fixed.	O-QIS, procella
Bug	QDC-4171	Values with attributes 255 and 128 are no longer shown in the eChart value chart graphic (Q-DAS browser-based products).	qs-STAT
Bug	QDC-4232	For the different types of limits, the colours of the bars are now displayed correctly.	O-QIS, qs-STAT
Bug	QDC-4268	The "Individual values" (5801) graphic has been revised to show the latest values.	procella
Bug	QDC-4283	It is now possible to create a file with a dot in the file name.	qs-STAT
Bug	QDC-4315	The measured value can now be stored and displayed again above a graphic in "upper info".	O-QIS, qs-STAT
Bug	QDC-4446	The special handling of the window area being switched to "All windows" when using the "Complete parts protocol" graphics is now deactivated.	qs-STAT
Bug	QDC-4465	The configuration dialogue for the "Operator Control Board" (OCB) graphic has been revised.	qs-STAT
Bug	QDC-4553	Using the "Allocate subordinate test plans" option generated an error message.	procella
Bug	QDC-4572	Optimisation for discrete DOE factors has been revised.	destra
Bug	QDC-4722	Q-DAS Tools Launcher failed to start when SQL Management Studio password for SQL login user was changed.	
Bug	QDC-4815	The test procedure in procella was in a faulty state.	O-QIS, procella
Bug	QDC-4846	The position of the alarm viewer in CMM Reporting was not saved within the window layout.	O-QIS
Bug	QDC-4849	Benchmark report graphics were not displayed in the Form designer.	Q-FD
Bug	QDC-4910	Additional data dialog was empty or contained special characters when displayed again.	
Bug	QDC-5021	Losing the contents of filter conditions when re-entering has been fixed.	qs-STAT
Bug	QDC-5076	Application did not start because the entry in the INI file used for mdi_form was too small.	EMPB, qs-STAT
Story	QDC-4165	Data compression for LT was sped up, in the case of measurement readings in the database starting with dates from 1970.	M-QIS Reporting
Story	QDC-4167	The logging of the amendment history has been extended.	M-QIS Reporting, M-QIS Upload, procella, qs-STAT

	Key	Changelog statement	Component/s
Story	QDC-4296	Q-DAS applications now display the Windows operating system and build number correctly.	qs-STAT

	Key	Changelog statement	Component/s
Bug	QDB-537	The application-specific configuration of the "number of measured values" for RTM is now correctly applied.	RTM
Bug	QDB-539	The number of rows and columns in the RTM could not be saved when changes were made.	RTM
Bug	QDB-559	The focus in the characteristics mask was often lost.	solaraMP Web
Bug	QDB-619	Beim Erstellen neuer Datensätze, ohne vorher neu erstellte zu Speichern kam ein Datenbankabbruch.	solaraMP Web
Bug	QDB-840	The beam that can now be inserted into the RTM has overlapped parts of the graphic when enlarged.	RTM
Bug	QDB-874	Missing icons were added, captions with line breaks were defined to make texts that were too long	qs-STAT Web
Bug	QDB-878	The dialogue of the type conversion was distorted	solaraMP Web
Bug	QDB-880	The e-chart value progression did not recognize the attribute 255 for deselected measured values.	qs-STAT Web
Bug	QDB-886	Overview graphics did not start from the first characteristic when clicked in the characteristics list, the focus was lost.	qs-STAT Web, solaraMP Web
Bug	QDB-898	Part data in the detailed view of the PLV remained in place and was not hidden or updated.	
Bug	QDB-983	Help information has been re-designed.	
Bug	QDB-1003	Save value mask after manual changes has been reworked.	solaraMP Web
Bug	QDB-1164	Navigation buttons in the parts protocol or the entire parts protocol disappeared during live operation.	RTM
Story	QDB-389	Guidelines for checking passwords revised.	