

Key	Changelog statement	Component/s
Bug QDC-874	The options for the value mask table can now be defined in the graphic styles.	qs-STAT
Bug QDC-1120	When changing the characteristics via the parts/characteristics list, an error message was displayed if a characteristic with R=0 was present.	qs-STAT
Bug QDC-2032	The graphic "characteristic benchmark" inserted in the overview/input mask did not display anything and generated an error message after confirmation.	O-QIS, procella
Bug QDC-2063	Opening the graphic "characteristic benchmark" caused an error message.	procella, qs-STAT
Bug QDC-2493	Symbol for removed outliers was no longer displayed.	qs-STAT
Bug QDC-2651	It was not possible to accept pending measurements. The pending measurements can only be confirmed after restarting the application.	O-QIS, procella
Bug QDC-2723	No overall assessment was carried out if only "Range smaller than n% of a bilateral tolerance" is set as a requirement in the evaluation strategy.	qs-STAT
Bug QDC-2765	A FireDAC error message occurred when copying test plans with characteristics grouped into characteristic groups. Bug fixed.	qs-STAT
Bug QDC-2789	It was not possible to select directory for archiving. Bug fixed.	M-QIS Reporting
Bug QDC-2791	Q-DM option "check data format" erroneously failed when applied to a correct written DFQ file and additionally moved this file to the erroneous directory.	M-QIS Upload, qs-STAT
Bug QDC-2795	Changing the number of operators in the characteristics mask caused an access violation.	solara
Bug QDC-2825	When the option to display control limits and individual values is enabled in a calculated SPC QCC, the symbols are drawn too large. Bug fixed.	qs-STAT
Bug QDC-2898	Characteristics for a special measurement were not taken into a special measurmnet if they were within a group.	O-QIS, procella
Bug QDC-2935	in the 64-bit Version no data collection via RS232 (Com) was possible.	procella
Bug QDC-3101	Changing the input/evaluation method from Type B to Type A for a REST component in the measurement process no longer changes the linearity component settings in the measurement system.	solara
Bug QDC-3251	The "Test plan" graphic is now displayed correctly for group measurement when a manual change between groups is used.	procella

Key	Changelog statement	Component/s
Bug QDC-3365	The manual user change within the application generated an error message. (Range Check Error)	procella
Bug QDC-3367	The "bad smiley" reporting job mistakenly sent emails/reports via the reporting system even though there were no incorrect measurements.	M-QIS Reporting
Bug QDC-3399	Pre-filtering by an inequality sign in K2016 at feature level results in an error message when reading the DFQ file. Error fixed.	M-QIS Upload
Bug QDC-3447	Pre-filtering by equals sign on k-field 2005 generated an access violation.	M-QIS Upload
Bug QDC-3449	Reloading a test plan from the database during a special measurement caused an access violation.	
Bug QDC-3507	The measurement procedure for special measurements was displayed incorrectly.	O-QIS, procella
Bug QDC-3529	The special alarm setting within the report assignment for reporting system is now working again.	M-QIS Reporting
Bug QDC-3588	When changing the module (CMM reporting to procella), an access violation occurred in the O-QIS application.	O-QIS
Bug QDC-3742	Additional data in a customer-specific report is now displayed correctly again.	qs-STAT
Bug QDC-3744	Creating and editing text with symbol characters in SQL text databases is now possible again.	qs-STAT
Bug QDC-3755	An access violation occurred when the destra application was closed.	destra